


KINETIC SCULPTURE

Your kinetic sculpture is made entirely of stainless steel and will maintain it's luster for years and years.



Slide bearing shaft into sleeve.
Stop when the top bearing is flush
with top of sleeve.

Do not make the alen screws too
tight! Turn them 1/2 turn and then
spin the sculpture to see if it turns
freely if it does turn them 1/4 turn
more.

For assistance please feel free to contact me:

Jim LaPaso

512-396-4041
jim@designsbylapson.com
www.lapaso.com